

MING.

top Angles

Surveyors

Received from Chief Surveyors

NAME *Stl T.S. M/Jerry M.O.P 5 B.A* Report *Sl* No. *48537***For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(Cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

Survey *1st Entry* When due *✓*


A. I. (Steel). "For Ferry Service on the Rivers Parana and Plata"—
 —"limiting seaward ports, Buenos Aires, Colonia"

Stl - Leaks

K, 6 B.H, Cleys A CP.

[Signature]

[Signature]
 1.11.28



© 2020

 Lloyd's Register
 Foundation

W/099-0099

Keelsons, No. each side

Two

 Fourth Deck, amidships, Angle, *□* or *□*