

8m.12.32.

5 E

2 JAN 1941

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME "BEGERIN"

Rpt. Bel.

No. 12832.

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Nature of Survey

~~DAMAGE~~ WEAR AND TEAR.

The main engine compressor cylinder found cracked, now renewed.

The crank case which was cracked has been welded, afterwards fitted with plates. *bolted over the welded parts.*

It is submitted the vessel is eligible to remain as classed without

a record of Survey ~~subject~~ as recommended.



© 2019

Lloyd's Register  
Foundation

*Hru*  
31.12.40

W11-0123

*Compressor cylinder opened up, examined*