

m.9,37.

1 - APR 1940

1

by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

NAME BRODWAL Rpt. MSL No. 10023

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

of Survey DAMAGE.

Damage through heavy weather

How repaired as follows:-

	Shell Plates	Main Frames	R. Frames	Floors & Bracket Floors	Inner Bottom Plates	Deck Plates	Beams
Renewed							
Moved and faired or repaired.....							
Faired or repaired in place.....							

Other items:-

Vessel afloat repairs effected to steering-gear & connections,
deck fittings and equipment.

is submitted the vessel is worthy to remain as classed without
Order of Survey

was
1-4-40



© 2019

Lloyd's Register
Foundation

W11-0164