

Received by Chief Ship Surveyor 12. 4. 02

Received from Chief Ship Surveyor _____

VESSEL'S NAME St. S. S. Sydney Report See No. 6821

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	<u>2/20"</u>	<u>Proportions</u>
Spar Sheerstrake . .	<u>✓</u>	<u>✓</u>
Description of Framing:— <u>Deep (Bulb angle) framing.</u> (viz., ordinary, deep, zed, channel or bulb-angle).		

This vessel appears to have been built in accordance with the rules and the approved plans, and it is submitted she is eligible to be classed * 100A1 as recommended.

* 100 A1 ("Steel")

1 DR (Stt) & deep framing

N.B = Cell DB a 76' u E 22' f 116' 403E FPT 34E APT 35E

FK 4BH Cell. Lloyd's A9CP P45 B97' F35'

C. D. J.
12/4/02



© 2021

Lloyd's Register
Foundation

W1100-0025