

THE SURVEYORS ARE REQUESTED NOT TO WRITE  
the Surveyor examine all the manholes, doors and their fastenings of the main boiler  
✓ and of the Donkey Boiler?  
? the aff  
scently lu  
fter end  
lubricate  
Sal  
stia  
T  
of both after  
low furnace of starboard after boiler was found damaged

are type

Connamethenshire

Indb. 13672

It is submitted that before this  
report receives consideration Messrs. Saltsman  
be requested to state in writing the <sup>new</sup> owners  
intentions as regards the <sup>new</sup> class.

IF IT IS SUBMITTED THAT THE ABOVE IS ACCEPTED TO BE THE CASE

W1102-0264

13/5/29

Lloyd's Register  
Foundation