

RETSIGER.



BUCHANAN,
ENGINEER SURVEYOR.

Mississippi S.B. 5

LLOYD'S REGISTER OF SHIPPING,

810 HENHEN BUILDING,

NEW ORLEANS, LA.,

Nov; 8th. 1918.

REC'D NOV 11 1918

ANS'D

The Secretary,

New York,

Dear Sir,

I am in receipt of your letter of the 1st:
inst: regarding the "ELIZABETH RUTH", and in reply,
I am awaiting a reply from the Builders for the
diameters of Propeller, and screw shaft; I may say,
however, that the screw shafts were made strictly in
accordance with the blue prints except that the ends
of the brass liners were tapered off to allow of
wrapping them to prevent salt water action on the
shafts, there are two separate liners on the shafts;

I know the pitch of the propellers is 7 ft:
but I am not sure of the exact diameter; I shall
advise you when I get the Builders answer.

I am,

Yours faithfully

M Buchanan

© 2020

Lloyd's Register
Foundation

W1104-0020