

Yacht "FLYING CLOUD"

Three plans shewing attachment of A brackets to hull structure submitted by the Genoa Surveyors.

It is submitted the Genoa Surveyors be informed it is noted that the shaft brackets are now made, and they be requested to point out to the Builders that a plan of these brackets was asked for in the Secretary's letter of the 8th March, when it was made clear on the plans that approval of the shaft brackets was contingent on the receipt of the requested plans. It is considered that plans should have been submitted as requested.

The arrangements now submitted appear to be substantially the same as originally dealt with on the 8th March and 21st May, which were not approved, and as the attachment of the palms to the hull structure is the crux of the matter, the Builders' proposals, therein, stated to be forthcoming later, are awaited. In the meantime the plans might be retained.

The Builders' attention might further be drawn to the fact that they have not yet submitted details of the support of the shafting where it leaves the hull, as requested in the Secretary's letter of the 8th March and embodied on the plans then approved.

Lr. 5/6/26

Ans'd. 10

3 Plans retained

10.6.26.

L.R.E.



© 2020

Lloyd's Register
Foundation

W1104-0303