

W1104. 0348

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME St S "DALRIADA"Report LnkNo. 18534**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/82.)

Nature of Survey 1st Entry

When due _____

✱ 100A - (Steel). With keelboard


1 D¹¹ (Stl - ws), 2nd D¹¹ (Stl - ws) in holds.

Cell D.B. & E 26', f 60' bot, Tanks at sides of tunnels 65t, F.P.T. 15t, A.P.T. 14t

F.K. B.K. 1½", 7 B.H., Cen...

B 90' F 56'.

It is concluded the riveting in the hulls of the bridge side plating is as approved, but the Surveyor should be requested to state if this is so.



© 2020

Lloyd's Register
Foundation

20.5.26.
20.5.26.