

3m.7.28.

1

Sent to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME Stl S LADY COMBE Report Stl No. 48294**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey P. Entry When due Revised Rule

✠ 100A.1. (Steel). Dredger } subject to steel deck being sheathed
 1 D (Stl) } with 2 $\frac{3}{4}$ Cement on vessels
 M.T. 15T, } arrival at Lagos.
 F.K, 5 B.H, Cem, Hays ACP.

Lloyd's Register
Foundation

W1105-0195

Foundation Plate on
Floors.....

Third Deck, amidships, Angle, E or F.....