

F.E.

Received by Chief Ship Surveyor 1. 3. 06

Received from Chief Ship Surveyor _____

VESSEL'S NAME St. Steam Trawler "Victor" Rpt. Abu No. 8631

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	<u>2/20"</u>	<u>Not required.</u>
Spar Sheerstrake . .	<u>"</u>	<u>"</u>
Description of Framing:— <u>Ordinary, increased to compensate for</u> (viz., ordinary, deep, zed, channel or bulb-angle). <u>omission of some frames.</u>		

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed $\pm 100 A 1$ ("Steel") "Steam Trawler" as recommended.

 $\pm 100 A 1$ ("Steel") "Steam Trawler"

/ DR.

W. B = DB f 25' 20t

BK 7½" 4BH Cam. Lloyd's A & CP

It should be pointed out to the Surveyor that the size of the warp required by Table 22 is 4" and not 4½" as stated in his report.

W1106-0049

C. H. J.
© 2021/06Lloyd's Register
Foundation