

THUR. 29 MAR 1906

Aberdeen

12th March 1906

James C. Surpin

the engine builders Messrs J. V. V. Lidgerwood
examine the Condenser of the S.S. "Victor" of
Peterhead, 201 tons tonnage, while lying in the Harbour
at Leroy on the 4th February 1906 after the vessel
had completed her trials in order to ascertain
the nature and extent of the damage the
cause of which has not stated.

On examination found the Condenser cracked
at each end at the back, the crack at the fore
end extending through the flange and five inches
into the body, that at the after end extending
through the flange and seven and a half inches into
the body.

Recommended that a new Condenser be fitted
and all corrections remade in order to place
the machinery in as good condition as it was in
before having sustained the damage in question.

James C. Surpin

Dec 2-0-0
Ler 10% 11-0
1-16-0 Paid 25/3/06



© 2021

Lloyd's Register
Foundation