

s.s. "ITAPAGIPE".

---

L.A.No. 3923.

The Boiler Survey became due 11,28 and the boiler has now been examined by a Surveyor appointed by Lloyd's Agent at Bahia who recommends that the boiler be removed ashore, and considerable repairs effected to it.



He further recommends that when these repairs have been carried out and before the vessel (which is laid up on blocks on the beach) is again placed in commission the boiler should be submitted to a general examination.

The Surveyor in his recommendation to the Committee states that the boiler is now in a bad condition and in his opinion is not eligible to remain as classed.

IT IS SUBMITTED that the vessel is eligible to remain as classed subject to the boiler not being used until repaired and satisfactorily reported on.

Delete pressure.

ARR

  
15.5.29.  




© 2020

Lloyd's Register  
Foundation

W1108-0161