

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C.

31st December, 1914.

E. Dear Sir,

With reference to Glasgow First Entry Machinery Report No.34689 in the case of the steamer "KINABALU", I have to point out that with a propeller 8'-9" diameter, the diameter of the screw shaft as per Rule should be 7.23", not 7.1" as stated in the report.


I am, Dear Sir,

Yours faithfully,

Secretary.

The Secretary,

GLASGOW.



© 2020

Lloyd's Register
Foundation

W1108-0190