

S.S. Koniabalu Gleep No 34689

It is submitted it should be pointed out to the Glasgow Surveyors that with a propeller 8' 9" dia, the diameter of the screw shaft as per Rule should be 7.23" not 7.1" as stated in their report

A.R.R.  
31.12.14

Lr: - 31/12/14

© 2020

Lloyd's Register Foundation

long. seams \_\_\_\_\_ Diameter of rivet holes in long. seams \_\_\_\_\_ Pitch of rivets \_\_\_\_\_ Lap of plates or \_\_\_\_\_  
Per centages of strength of longitudinal joint \_\_\_\_\_ rivets \_\_\_\_\_ Working pressure of shell by rules \_\_\_\_\_ Size of manhole \_\_\_\_\_  
plate \_\_\_\_\_