

15 FEB 1930

s.s. "EILENAU".

-----  
Lon. 94754a.  
---


To complete the Main Boiler Survey due 6,29 the safety valves require to be adjusted under steam.

In reply to enquiry the Society's Surveyor at Bremen now forwards a letter from the Owners in which they state they have decided not to renew the classification with this Society and have had the vessel classed with the Germanischer Lloyd.

IT IS SUBMITTED that in the circumstances the vessel's class be withdrawn from the Register Book, and three dots (...) inserted in lieu thereof, indicating withdrawal of class at Owners' request.

Withdraw class.

Insert ...

  
15.2.30.



© 2020

Lloyd's Register  
Foundation

W115-0133