

sp "Taizan Maru".

It is submitted the Yokohama Surveyors be informed that it is concluded a spare set of feed & bilge pump valves has been placed on board, but as this is not stated in the report they should state whether this is correct.



© 2020

W.D.

27/11/18

W107-0084

Working pressure by rules 210 Steam dome: description of joint to shell

Diameter X Thickness of shell plates X Material X Description of longitudinal joint

Thickness of shell by rules Crown plates Thickness