

SURVEY ON SHIP

I certify that at the request of Messrs. The Cavalla River Co. Ltd., Lloyd's Agent for Monrovia, I surveyed the Twin Screw Motor-ship "DUVALLA" on the fifth day of June 1930 afloat in the Junk River at Marshall, Liberia.

In my opinion this vessel was sound in every respect with the exception of the STEMPOST which was found to be defective at the waterline outside. No trace of damage could be found above the waterline or inside the hull. owing to the survey being conducted afloat I have no means of knowing how far the damage extends beneath the water. I recommend that this part be examined at the first opportunity.

Every part was examined thoroughly by me and the engine, screws anchors chains, etc., were found to be in sound condition.

I am of opinion that the vessel at the time of survey was in fit state to proceed to the nearest repairers, which is situated at DAKAR and after the repair mentioned above has been effected no difficulty should be experienced in her obtaining a clean Certificate of Fitness.

Dated June sixth 1930  
at Monrovia, Liberia.

.....  
R. GRUNER MASTER and appointed  
Surveyor to  
Germanischer Lloyd.

Witness to Signature  
OR CAVALLA RIVER CO. LTD.

A. A. *A. A. [Signature]*  
AGENT,  
Lloyd's Agent.



© 2021

Lloyd's Register  
Foundation

W1118-0198