

N.B.—All alterations in the existing records should be underlined.  
If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing,

CHARACTER.  
\* for Special Survey.  
Date of last Survey and of Periodical Surveys.

TELEGRAMS: FIXTURE, CARDIFF.

CODE:  
SCOTTS, 101<sup>st</sup> EDN.

TELEPHONES CARDIFF 2970.  
(AFTER HOURS) " 391.

**HENLEY STEAMSHIP CO., LTD.**

MANAGERS:  
HENLEY (MANAGEMENT) LTD.

38, MOUNT STUART SQUARE,  
CARDIFF.

ED/JHE

AND AT 5/7, ST MARY AXE, LONDON, E.C.3.

24th August 1931.

Messrs., Lloyd's Register of Shipping,  
CARDIFF.

Dear Sirs,

**"CHISWICK MANOR".**

-----  
Confirming telephone conversations regarding Survey of this steamer, as we explained the vessel has been laid up at CARDIFF since January last, and so far as we can see at the moment, there is absolutely no chance of her running owing to the low level of rates, so that under these circumstances, we are unable to make any arrangements for the commencement of the Survey.

We should be glad if you will please advise your Committee and ask them to be kind enough to allow us to postpone it until such time as there is a general improvement.


Thanking you in anticipation, we are,

Yours faithfully,

FOR AND ON BEHALF OF  
HENLEY STEAMSHIP COMPANY LIMITED

HENLEY (MANAGEMENT) LTD.

MANAGER



W1121-0195

A1  
31  
2-  
fatto  
ard (if  
ip and  
hom ?  
31)  
spe  
le  
t  
3.  
Lal  
nd  
tems :—  
Copper,  
(ste  
Whe  
Boats  
Masts  
Conditio  
(stat  
Sails.....  
Equipme  
Anchors  
Cables ( )  
" le  
" R  
Hawser  
Standin  
el in the  
remain s

W1121-0186