

Capacity \_\_\_\_\_ tons. FPT \_\_\_\_\_ tons; APT \_\_\_\_\_ tons; MT \_\_\_\_\_ feet \_\_\_\_\_ tons.

N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing,

CHARACTER.  
\* for Special Survey.  
Date of last Survey and of Periodical Surveys.

Port of Cardiff

Oct. 24<sup>th</sup> 1932

REPORT ON MASTS, SPARS, AND RIGGING.

Sirs,

Having, in accordance with your instructions, examined Masts, Spars, and Rigging, and Iron Work of same, of the "Schiswick Manor", on the 22<sup>nd</sup> September 1932 I have to report that I found all in good condition except as under:-

Foremast

Forestay requires renewing

Wood topmast sprung, requires two steel clamps fitted each about 5" wide.

Foremast backstay, on Port side, shackle at deck to renew.

Main Mast

Main stay requires to be renewed.

D. Jenkins

Surveyors, &c.  
Lloyd's Register of Shipping,  
Cardiff.



© 2020

Lloyd's Register  
Foundation

AI  
31  
2-  
Batten  
ard (if as  
hip and no  
whom? ✓  
31).  
spac  
+ ead  
a th  
B. t  
late  
end  
Items :-  
Copper, or  
(state  
When  
Boats  
Masts, Yal  
Condition,  
(State  
Sails  
Equipment  
Anchors, N  
Cables (sta  
" leng  
(  
" Rule  
Hawser &  
Standing a  
essel in the E  
o remain as