

2500,3,23.

1

Sent to Chief Surveyors 20. 6. 31

Received from Chief Surveyors

27. 6. 31

VESSEL'S NAME *Stl m/s Barforn*

Report *sol*

No. *8327*

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)


Nature of Survey

*Equipment*

When due

*Noted*  
*[Signature]*  
 27. 6. 31

*[Faint, mostly illegible text from the reverse side of the page]*



depth & thickness of Intercostal Plate...	1600 x 12.5			
Top Bulb Angles	280	90	12.5	single
Angles to Shell	150	150	13	appx. 140 x 140 x 14

Spacing			
Poop Deck, Angle, E or C	230	90	12.5
	230	90	11
	200	75	10

*[Vertical text from the right edge of the page, including 'Est. Dal', 'er', 'gen', 'float', 'dry', 'IN SHIP', 'x12', 'o 13', '30 15', 'e 15', 'T. flush', 'Plan', '0 x 14', '14', '20', '70 10.5', '70 11', '25']*