

Date 3rd. May, 1941

No. of Items.....

SPECIFICATION of REPAIRS s.s. "BELGRAVIAN".

A.S. 187-5,000-5/40 (2680)-EW

MAIN ENGINE REPAIRS.

101. H.P. Piston Rod Metallic Packing to examine and adjust.
102. L.P. Piston Rod Metallic Packing to examine and adjust.
103. Exhaust Turbine Tac ometer, to repair and test.

BALLAST PUMP.

104. Steam & Exhaust Piston Slide Valves to renew.

FEED HEATER.

106. Steam Control Cock. New plug to supply and fit.

EVAPORATOR.

107. Vapour Valve. To overhaul (shut down job).

BOILERS.

117. 60 Main boiler firebars.
118. 3 right, 3 left Baffle Plates (side).

STONEHOLD WORK.

110. Starboard Boiler smoke, 3 batches to renew.
Box Door Catches.

ENGINE ROOM GEAR.


112. Engine Room Portable Hand Pump. Suction pipe to fit and adaptor required to fit to discharge flange, to suit Engine Room Hose.

PRESSURE GAUGES.

113. Dynamo Eng. Oil Pressure Gauge to repair & test.
Turbine Inlet Press " " " "
Vacuum Gauge " " " "
Auxiliary Exhaust " " " "
Starbd., Boiler Steam " " " "

THERMOMETERS.

114. Turbine Bearing. 4 to repair.
400° Therms. Feed Pump. 2 to repair.
240° Hot Well. 2 to repair.



also
Air pump S 1/2 Valve overhauled
Turning Engine Steam line
Afterside joints in de good
W. G. Drains P.R.S. & P. Boilers
made good.

hcf.

Travelling Expenses (if chargeable) £.....

Second Surveyor's Fee (if any) £.....

Committee's Minute

FRI. 13 JUN 1941

19

Surveyor to Lloyd's Register of Ship

© 2021

Lloyd's Register
Foundation