

Fees paid

F.E.
(FBD.)

Received from Chief Ship Surveyor

Rpt. Sld, No. 32788

⁽⁴⁾ The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/92.*

Depth "d" -

Proportions $= \frac{L}{D}$ 11.15

Sheerstrake As approved.

D to shelter dk 36.33! D to 2nd dk 27.83! D for scantlings 35.83'
(ie. to 8' above 2nd dk.)

This is a complete superstructure vessel with tonnage opening and a sister vessel to the "ROYAL SCEPTRE", "ST. ELWYN", BRETWALDA, and "ARGYLL".

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ~~X~~ 100 A1 "with freeboard"

1 Dk & Shelter dk.

Cell DB 289' 975t, Tanks at sides of tunnel 390t FPTs 324t APT 145t
FK, 6 BH (Coll to Shelter dk, 5 to 2nd dk), Cem, Lloyds A & CP.
F 36'.

O.L 431.8'

E.S.D.

a +

f.c.d
6.2.40