

REC^d 17 JAN 1923

The Secretary.,
Lloyds Register of Shipping.
London.

ANS^d _____

and

W1124-0133

To Chief Surveyors 18.1.23

Received from Chief Surveyors 19 JAN 1923

VESSEL'S NAME Steel S.S. "Glynarthen" Report Sou No. 10740

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24.6.92.)

Age of Survey S.S. No 1


When due 11.22

It is submitted the Southampton Surveyors should be requested to state whether the requirements of a Special Survey p. 3 were complied with when the vessel was under Survey at their port in 1920 and whether, in their opinion, a notation of SS. Sou. 3-10.20 might be assigned if desired by the Owner

The Certificate of Classification, to be endorsed "Cargo battens not fitted," and the same notation to be printed in the Register Book.

M
19-1-23

To Mr. L.A. Hill
Barrister
Sou.



© 2021

Lloyd's Register
Foundation

| | | | | | | |
|----------------------------|----|----|--|--|--|--|
| Angles on upper edge | 24 | 24 | | | | |
| Spacing | 24 | 24 | | | | |

* If Iron or Steel Deck, state if whole or part, and if Wood Deck is