

VESSEL'S NAME

BRITISH CAPTAIN

Report

N.Yk.

No. 41153

## For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case

Im.11.36.

31 OCT 1941

H.

Received 28.10.41.

Answered

Extract from letter dated 23.9.41. received from

Wm. Bennett, Esq. New York.

Original letter with "3"

Vessel's Name S/S "BRITISH CAPTAIN"

N.Yk. 41153. The Surveyor confirms that the vessel, in his opinion, is efficient for a period of 12 months.

*Noted  
filed*

W1124-0165

© 2021

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book. In this survey, thus, for example:—".....to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and surveyed, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

*This vessel is in my opinion in a fit condition to remain as classed in the Register Book for a period of 12 months and to have a notation of Examination*

need  
boiler  
Tila  
carv  
sand  
mu  
and  
board  
led.  
ne a  
M.  
(on board)  
Month  
s, &c.  
w ascertain  
wedges r  
etter  
of  
e if now re  
30  
(on board)  
Rule length 30  
ain Locker  
wsers & Warps  
anding and Running E  
ils