

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report

When handed in at Local Office

Port of

London

No. in
Reg. Book.

Survey held at

Date, First Survey

Last Survey

19

81840

on the ~~Wood~~ ~~Iron~~ or Steel

TWIN. S. "PRIMULA"

TONNAGE

Built at

Savona

By whom

G. A. Elli. Migliardi When 1921

GROSS

2311

Owners

E. Mazza

Owners' Address

(if not already recorded in Appendix to Register Book).

UNDER DE.

1758

Managers

NIN POMONA

Port belonging to Savona

Surveyed Afloat or in Dry Dock?

Name of Dock

Destined Voyage

W/B=CellDBorDBa

feet; uE&B

feet; f

feet

total capacity

tons. FPT

tons; APT

tons; MT

feet

tons.

Particulars of Classification (which must be inserted
precisely as in Register Book & Supplements).CHARACTER.
For Special Survey,
Date of last Survey and of
Periodical Surveys.Machinery and Boiler
Survey
(including date of N.B. if any).

+100A1

6,29

+L.M.C.

4,26

DB 7,28

+L.M.C(M) 1,28

T.S. 7,28

OIL ENGINE

Society's Freeboard (if assigned) as
painted on Ship and now verified

ft. 1/2

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS:—

Renewed

Removed and Faird or Repaired

Faird or Repaired in place

Shell Plates.

Frames.

R. Frames.

Floors.

Beams.

Str. Plates.

Dk. Plates.

Other Items:—

PRESENT CONDITION OF THE

Decks

Caulking of Decks

Coamings

Beams & Fastenings

Outside Plating

Breasthooks

Transoms

Frames

Reverse Frames

Longitudinals

Transverses

Floors

Keelsons

Stringers

Inner Bottom Plating

State if Tanks have been examined inside

State if Tanks now tested

Bulkheads

Ceiling

Cement or Asphalt

(State which.)

Rudder

Steering gear and its connections

Windlass

Have Pumps now been examined and found effi-

cient?

Have Sluice Valves now been examined and found

efficient?

Have Watertight Doors now been examined and found

efficient?

Have Ventilators and their Coamings been examined

and found efficient?

Dblng. Plates under Sounding Pipes

Engine Room Skylights

Coal Bunkers, Open'gs, Lids, &c.

Scuppers

Cargo Hatchways

Hatches

Planking of Wood Vessels

Caulking

Treennails

Breasthooks & Stemson

Transoms, Pointers, & Crutches

Timbers of Frame at openings

Ditto ditto at other places

Stringers, Clamps & Shelves

Salting

(State if examined.)

Copper, or Y.M. of Wood Vessels

(State if on felt).

When put on, Month Year

Boats

Masts, Yards, &c.

Condition, how ascertained

(State if wedges removed)

Sails

Equipment letter

Anchors, No. of

Cables (State if now ranged)

,, length size

,, Rule length size

Hawser & Warps

Standing and Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and ptND24, &c."

Survey Fee (per Section 20) £

Special Damage or Repair Fee (if any) £

Travelling Expenses (if chargeable) £

Second Surveyor's Fee (if any) £

Fees applied for,

19

Received by me.

19

Committee's Minute

Character Assigned

Lr. Com. 4/9/30

Write for (copy)

TUE. 2 SEP 1930

Expunge class

with

Surveyor to Lloyd's Register of Shipping.

General Committee

Thursday, 4th September 1930

Classing Committee

decision confirmed

Lloyd's Register

Foundation

Is Certificate required? If so, to be sent to

W1123-0050