

*D 87 Bottom 9*

Steel Screw Ketch "PONTUL EUXIN"; No.59193 in Register Book;  
136 tons gross; Built 1924. Port: Constanza.  
Owners: "Pmntul Euxin" Soc. Anon. (Manager: Nicolas Hiott).  
Classed: 100A- 6,25 LMC.6,25  
For fishing purposes T.S.10,28.  
S.S.No.3-6,25

-----

The 2nd S.S.No.1 became due on this vessel (after an early No.3) in June, 1929.

No reply was received to the usual Notice addressed to the Owners on the 15th July, 1929, and on the 6th June, 1930, the Society's Surveyor at Braila was requested to ascertain the Owners' intentions regarding the carrying out of this survey.

In the absence of any reply the Braila Surveyor was asked to cable this Office regarding the matter and he cabled on the 17th July that he had written to the Owners on the 14th and 30th June and 10th July, 1930, but had received no reply from them.

In the circumstances the Committee gave instructions that the Owners should be informed that arrangements must be made for the survey to take place forthwith in order to entitle the vessel to retain her class. The Owners were accordingly informed to this effect in a letter dated 18th July, to which no reply has been received.

The Braila Surveyor also writes on the 16th July that he has again communicated with the Owners' Head Office and has received no reply.

The Classing Committee had this case before them on Tuesday, 12th instant, when they decided to give instructions for the vessel's class to be expunged from the Register Book with a red line (~~8.30~~), indicating non-compliance with the Society's Rules.

14th August, 1930.

© 2020

Lloyd's Register  
Foundation



Lloyd's Register  
Foundation

Dear Sir,

1578/30