


W1127-0133



BURNS, PHILP & COMPANY LTD

CAPITAL £2,000,000

AUSTRALIAN MERCHANTS & SHIPOWNERS

HEAD OFFICE, 7 BRIDGE ST. SYDNEY, N.S.W.

SYDNEY 15th July, 1930.

G.P.O. BOX No. 543 B

ADDRESS: "BURPHIL"

BRANCHES:

OFFICE: "LONDON HOUSE"
ST. MARTIN'S LANE, E.C. 3

FRANCISCO OFFICE:

FOUR BUILDING
& CALIFORNIA STREETS

THURSDAY ISLAND
TOWNSVILLE
PT. MORESBY, PAPUA
SAMARAI, PAPUA
RABAU, NEW GUINEA
AUCKLAND, N.Z.
WELLINGTON, N.Z.
SOURABAYA, JAVA
SAMARANG, JAVA

IN AUSTRALIA AND
NEW ZEALAND FOR
THE SOUTH SEA CO., LTD.

NEW HEBRIDES
VILA

SOLOMON IS.
MAKAMBO
GIZO
FAISI

GILBERT IS.
TARAWA

NAURU

NORTH-EASTERN RAILWAY

THROUGHOUT THE WORLD

Messrs. Lloyd's Register of Shipping,

SYDNEY.

Dear Sirs,

S.S. "MAKAMBO".

I wish to inform you that the Directors
of this Company have decided not to proceed with the
reclassification of the "MAKAMBO".

Yours faithfully,
For BURNS, PHILP & COMPANY, LIMITED.

A. Broughan

Assistant Superintending Engineer.

Sydney, N.S.W.

RECEIVED
5 JULY 1930
ANSWERED

SEEN
E.L.G.
J.C.B.
B.P.Z.

LOYD'S REGISTER
RECEIVED
18 AUG 1930
LONDON



© 2020

Lloyd's Register
Foundation

Referred to Mr. S. A. Hill.

16 AUG 1930

unfounded

FOR BUREAU OF COMMERCE, BUREAU OF MARITIME SAFETY

RECEIVED
U.S. DEPARTMENT OF COMMERCE
BUREAU OF MARITIME SAFETY
WASHINGTON, D.C.

RECEIVED

RECEIVED

RECEIVED

© 2020

Lloyd's Register
Foundation

(The Surveyors are)

Committee
Character

Special Damage
(per Sec)
Travelling Exp
Second Survey

this survey

General

Inner Bottom Pl

Stringers

Keelsons

Floors

Transverse

Longitudinals

Reverse Frames

Frames

Transoms

Breasthooks

Outside Plating

Beams & Fastenings

Coamings

Caulking of Decks

Decks

PRESENT COND

Removed a

Removed

Renewed

SUMMARY OF D

REPAIRS, OR