

COPY.

# Lloyd's Register of Shipping.



Port St. John's, Newfoundland,

October 29th, 1942.

This is to Certify that

T. O. MORRIS

the undersigned Surveyor to this Society did at the request of the Master, Captain J. Evans, attend on board the Steel Screw Steamer " EMPIRE LEOPARD ", 5676 Tons Gross Register, of London, as she lay afloat in St. John's harbour on the 6th, October, 1942, and subsequently, for the purpose of ascertaining the nature and extent of repairs necessary to steering engine and windlass.

UPON EXAMINATION FOUND:- Steering engine piston rod thread stripped in crosshead, aft side; temporary repairs effected at sea by fitting pin through crosshead and piston rod.

Hand steering dog clutch seized.

Windlass examined in way of main wheel on gypsy shaft, 4 teeth found to be fractured, and pinion wheel slightly out of mesh. Main Engine M.P. balance piston cylinder barrelled and piston slack.

REPAIRS NOW CARRIED OUT:-

Steering engine piston rod and crosshead renewed, aft side. Forward side opened up in way of crosshead and found to be in satisfactory condition.

Hand steering clutch and shaft overhauled and made workable.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:-

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."



COPY.

## Lloyd's Register of Shipping.

S.S. "EMPIRE LEOPARD".

-2-

29/10/42.

Windlass main wheel teeth repaired and pinion wheel  
dressed to suit.

Windlass examined under working conditions and  
found satisfactory. M.P. balance cylinder rebored & new piston fitted.

The above repairs have been carried out to my  
satisfaction.

Surveyed the Steel Screw Steamer "EMPIRE LEOPARD"

T. Shorris

3676 Tons Gross Register, of London, as she lay afloat in  
St. John's, harbour on October 6th, and subsequently,

SURVEYOR TO LLOYD'S REGISTER.

and that I have transmitted to the Committee of Lloyd's  
Register of Shipping, London, a Report, stating that all repairs  
recommended by me have been completed to my satisfaction, and  
that I have Recommended that she be continued as now  
classed without fresh record of survey,

being fit to carry dry and perishable cargo, subject to  
outstanding items of survey being carried out,

T. Shorris  
Surveyor to Lloyd's Register.Register Book.)  
VoyageDate of Classification (rel  
to the Register Book)Years  
and of  
expired.

1-42.

11-41

OIL FUEL

funnel(s) ✓

1 under steam

under steam?

oilers? ✓

oilers? ✓

Boilers? ✓

Boilers? ✓

balance fitted at the aft

and it being efficiently lu

tured at the after end

and efficiently lubricate

of after bearing of sc

and power fitted

of repair

of side, the

chain

Tow

tion, s

and

consequent

S. 9, 11, B.

on

consequent

S. 9, 11, B.

on



© 2020

Lloyd's Register

W028-0046 2/2

T. Shorris

Engineer Surveyor to Llo