


AMERICAN BUREAU OF SHIPPING

Date **Sept. 28, 1918.**

REPORT No. 29	REPORT ON CASTINGS OR FORGINGS		PORT OF Chicago.
VESSEL Emergency Fleet	INTENDED FOR SHIPBUILDER Federal Ship Building Corp.	SHIPYARD HULL No. Hull 8	
STAMPED <div style="border: 1px solid black; padding: 5px; display: inline-block;">A.B.  No.</div>	ENGINE BUILDER	WORKS ENGINE No.	
	OWNER Emergency Fleet Corp.	OWNER'S CONTRACT No.	
	PURCHASER Federal Ship Building Corp.	PURCHASER'S ORDER No. 1382	
ACCEPTED (Date) 8/19/18	MANUFACTURED BY American Bridge Co. Gary, Indiana.	MANUFACTURER'S No. 61F1663	
SHIPPED (Date) 8/31/18	FOR (State Structure) Turbine Engines	WEIGHT 28165	
INVOICE No. 8452	PROCESS OF MANUFACTURE OH Forgings	ANNEALED	

DESCRIPTION	PIECE NUMBER	HEAT NUMBER	Test Piece Area	TENSILE		% Elong. in	REMARKS BENDS, ETC.
				Beam	Per Sq. In.		
1 Line Shaft	16	162					For Hull #8
1 "	15	286					" #6
1 "	16	296					" #6

COPY

FOR LLOYD'S
REGISTER
OF SHIPPING

Particulars of Drop Testing, Slings and Hammering	The above shafts were tested, and inspected by me, after machining at above manufacturer, and found satisfactory.
1st Visit 8/19/18 Last Visit No. of Visits 1 day Fees \$40.00 Expenses \$1.20 TOTAL	<p>I have to report that the above mentioned Finished shafts have been tested by me in accordance with the requirements of the Rules as noted.</p> <p style="text-align: right;"><i>H. Guldstrand</i> SURVEYOR</p> <p style="text-align: center;">CHIEF SURVEYOR</p>

© 2020

W1128-0086