

SR 1, etc ~ Good deck plating (20s.) special

Caprice Star

LW 118589

No CL Spec
© 2020



Lloyd's Register
Foundation

WH28-025A

" " In way of sidelights
frames where eye good

Windlass.....
Have pumps been examined and found effi-
cient?

Hatches
Planking

6m,11,38.

Received by Chief Engineer Surveyor

VESSEL'S NAME

The remarks of the Chief Engineer Surveyor are desired on this case

("The endorsement to contain a succinct summary of any repairs that have been required to bring out clearly any exceptional features in connection with the case, so that they may be presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/12.)

SPECIAL SURVEY OF ENGINES AND/OR

Nature of Survey

Lloyd's Register
Foundation