




Examined port donkey boiler internally & externally  
 with safety valves, manways, manholes, door fastenings,  
 Oil fuel installation, valves, pipes & control gear examined  
 copy of Interim certificate issued herewith attached

To complete the D.B.S. - the port donkey boiler safety valves  
 require to be adjusted under steam.

29-5-22  
 20-5-22  
 19-5-22  
 18-5-22  
 17-5-22  
 16-5-22  
 15-5-22  
 14-5-22  
 13-5-22  
 12-5-22  
 11-5-22  
 10-5-22  
 9-5-22  
 8-5-22  
 7-5-22  
 6-5-22  
 5-5-22  
 4-5-22  
 3-5-22  
 2-5-22  
 1-5-22



M/S "Empire Star"

Sketch showing position  
 of tween deck bulkhead:

Siv Rept No. 118589.

Noted  
 W.A.  
 9/1/22  
 Now a Casualty