

17 MAR 1943

1

Sent to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME "ESSO BATON ROUGE" REPORT Bal. 7807
Gal. 4356 No.

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey Dmg. & 1st. S.S. No. 1 When due 7.42

Subject to permanent repairs to (holed)
stem plate in 4th strake below sheer (s.s)
at the next dry docking.

Wals
11.3.43

The Baltimore Surveyors should be informed it is concluded the Deep Tank forward has been dealt with as required for the Special Survey. They should also be referred to their 1st. Entry Report No. 6582 and informed it is not understood why the diameter of cables as originally supplied and now on board should be reported as being $2\frac{1}{2}$ " dia. instead of $2\frac{1}{4}$ " dia.

Wals 16/3/43



© 2020

Lloyd's Register
Foundation

W1131-0082