

TELEPHONE No. 3008 NEWPORT.

## Lloyd's Register of Shipping,

Midland Bank Chambers,  
Bridge Street,

Newport, Mon. 2nd. February, 1943.


Dear Sir,

In reply to your classing letter of the 29th. ultimo. regarding report No.24730 on the steamer "EMPIRE TOWER", we have to state that the electric welding repairs to the solepiece of the stern frame and rudder plates were specially examined and found efficient, also that the number of bower anchors on board is two and the length and diameter of chain cable is 255 fathoms (9 lengths port and 8 lengths starboard), diameter varying from 2.1/16 to 2.1/8".

We are, Dear Sir,  
Yours faithfully,  
The Surveyors,

The Secretary,  
WOKINGHAM.

per.



Lloyd's Register  
Foundation

*arrangement for gunners has now been fitted in the bridge space*



H  
RST

Noted  
GMM

3-2-43

23 FEB 1943

W



© 2020

Lloyd's Register  
Foundation

Damage  
RCW  
Renew  
Remove  
or  
Failure  
in  
Other