

(Received at London Office.....19..)

No. Place **BILBAO** Date **26th April 1933**

We request that the Committee of Lloyd's Register will instruct ^{auxiliary} the Society's Surveyors to Specially Survey during Construction the ~~Hull~~, Engines and Boilers of the Vessel No. **97** building by Messrs. **Cia. Buskalduna** Const. y Reparación de Buques for Messrs. **Cia. Trasmediterranea** of Tons. Length Breadth , Depth

intended to be Classed

We undertake to arrange for every facility to be given to the Surveyors to carry out the duty in question, and we agree to pay the fees for the Surveyors' services, in addition to the actual travelling and other expenses incurred by the Surveyors in connexion therewith.

This request is made upon the terms of the Rules and Regulations of Lloyd's Register of Shipping, which provide that:—

While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents of the Society.

Engine Makers

SOCIEDAD ESPAÑOLA DE CONSTRUCCION NAVAL

Astilleros y Talleres de Gestaio

Boiler-Makers

Signature

A. N. Pillelón

Jefe del Departamento de Maquinaria

To the Secretary,

Lloyd's Register of Shipping,

71, Fenchurch Street, London. E.C. (3)

Sho auth
2/5/33

Lloyd's Register
Foundation

W1132-0136

Are the lubricating arrangements shielded that they cannot be accidentally earthed, short circuited, or touched **Yes**