

120 AUG 1942

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME "FREDERIKA LENSEN" REPORT Hfx. No. 4094

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.


"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The class is subject to (a bower anchor being supplied).

The HALIFAX N.S. Surveyors report the vessel afloat and repairs effected to (cracked) windlass frame. The Surveyors recommend the windlass frame castings (p & s) be specially examined on arrival at a U.K. Port. ADVISE SURVEYORS.

hake  
movements  
It is submitted the vessel appears worthy to remain as classed subject as recommended and (as above).

As now, subject etc.



© 2021

Lloyd's Register  
Foundation

W1132-0183