

Frederika Lensen

F.E.

Received by Chief Ship Surveyor *27. 12. 12*

Received from Chief Ship Surveyor

VESSEL'S NAME

M. S. S. "Trevaylor"

Rpt.

Nwe.

No.

63454

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No.

78. 49

Depth "d"

24. 29

Framing: Table No.

3 page 16

Description

Built angle as approved

Longitudinal No.

28994

Proportions

Length


Depth

*10.4**Bridge*

Deck Sheerstrake

as per Rule

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

*+ 100 A. 1 ("Stub") as recommended**+ 100 A. 1 ("Steel")**1 Dk (p^t Sm - p^t SK)**M. P. Bull Lda 119 "E 26" f 163' 987t a P 162t**P. K. C. P. H. C. m. Logos A 161 P 33 B 226 F 34'*

Lloyd's Register

Foundation

W1132-0186

Angles on upper edge