

Was a damage report made by anyone else? If so, by whom? ✓

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? No.

fitted for oil fuel

"

"

Donkey "

"

"

✓

COPY

W1133 - 0072

Lloyd's Register of Shipping.

High Close, Wokingham, Berks.

12th October, 1942.

Dear Sirs,

With reference to the case of the steamer "HOBBEEMA", I beg to acquaint you that the Committee have now had before them a report received from the Society's Surveyors at Liverpool from which it appears some minor machinery repairs have been effected.

The Classification Survey has not been advanced at this time and no alteration is being made to the memorandum in this office regarding the case.

I am, Dear Sirs,

Yours faithfully,

The Netherland Shipping & Trading Cte.
Technical Dept.,
5/6, Crosby Square,
Bishopsgate, E.C.3.

/Ld.,

Copy to:- British & Continental
Clerk to the
Classification Committee.

Lloyd's Register
Foundation

*valve seats required machining, examined on com
the machine condition and found to be satisfactory*