

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report. 24/5/02.)

2m,10,30.

4 E

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME *HOB BEMA*, Ex *EMPIRE CHEERNA*. Rpt. *Full* No. *51618*

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report. 24/5/02.)

Nature of Survey REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH

Classification Survey advanced
Locking

Subject to the main machine heading being examined before the end of 9.43.

mem.

20/7/42

© 2020

Lloyd's Register
Foundation

W1133-0075

and a reply should be requested.