

ONE: CENTRAL/6610.



Lloyd's Register of Shipping,

Ocean Chambers, Lowgate,

Hull, 20th September, 1924,

LLOYD'S REGISTER
Recd. 22 SEP. 1924

Ans'd.

LONDON

Dear Sir,

In reply to your letter of the 18th inst regarding the First Entry on the Steam Trawler "ST DONATS" I regret the shearstroke butts are stated to be lapped, these butts are strapped as indicated on the approved midship section.

With reference to the other queries I beg to state:-

That the decks were not tested as it has not been the practice to test the deck of trawlers.

That the bulkheads were not tested as it has not been the practice to test bulkheads.

The testing of bulkheads is a requirement of the revised Rules and in accordance with the Secretary's letter dated 23rd April 1923, the practice adopted before the issue of the revised Rules has been carried out.

A copy of the Midship section and profile were forwarded with the First Entry Report as stated thereon.

I am, Dear Sir,

Yours faithfully,

Henry A. Ribb
Lloyd's Register
Foundation

The Secretary,
London E.C.3.

© 2021

W 1136-0102

Bracket Floors, breadth and thickness at
middle line.....

Forecastle Deck, Angle. F or E.....

Referred to the Chief Ship Surveyor.

RAM.


22 SEP 1924

WKS
2-10-24

Handwritten initials/signature

Vertical text on the left side of the page

Main body of the document, containing several lines of text, likely a report or correspondence. The text is mostly illegible due to fading and bleed-through.



© 2021

Lloyd's Register Foundation

Faint vertical text on the right side of the page, possibly bleed-through from the reverse side.