

Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

NAME "STAD MAASTRICHT" Rpt. Sws No. 22550

Marks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(¹The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. —Extract from Sub-Committee's Report, 24/5/92.)

The SWANSEA Surveyors report the vessel afloat and on account of damage through collision, the aftermost plate in 3rd strake below sheerstrake (p.s.) was found pierced.

Temporary repairs have been effected, and the Surveyors recommend this plate, together with the starboard boundary bar in way, be permanently repaired at the first convenient opportunity.

It is submitted the vessel appears worthy to remain as classed without record of survey, subject as recommended.

As Now, Subject, etc.



© 2021

Lloyd's Register
Foundation

W1136-0121

length
(on board)