

## REPORT OF SURVEY FOR REPAIRS, &amp;c.

of writing Report 27 Oct 40 when handed in at Local Office 28-10-40 Port of Swansea  
Survey held at Swansea Date, First Survey 12-10-40 Last Survey 16-10-1940  
Book. (No. of Visits 3)

3828 on the Wood, Iron or Steel STAD MAASTRICHT  
Built at Belfast By whom Harland & Wolff Co When 1924 4  
Owners Halcyon-Lijn N.V. Owners' Address  
Managers Port belonging to Rotterdam

eyed Afloat or in Dry Dock? afloat Name of Dock  
BorDBa feet; uE&B feet; f feet  
capacity tons. FPT tons; APT tons; MT feet tons.  
Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

Only alterations in the existing records of tanks should be inserted.  
All alterations in the existing records should be underlined.

Report, No. 53627 Port

CHARACTER.  
% for Special Survey.  
Date of last Survey and of Periodical Surveys.

HULL 11 Shells 100% H.M.C. 6.37  
with freeboard 8.40  
SS H.M.S. N°3 - 6.37  
B5 8.40  
T5 CL 7.40

Fitted for oil fuel 4.24 T.P. above 150° 7

age cases where the Surveyor has not made a special damage report he is required to state whether he  
ered his services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? If so, by whom?

IRS, OR EXAMINATION AS PER RULE, FOR Temporary repairs after damage stated  
Have been sustained when the vessel was struck by  
M. Trawler "Lady Eleanor"

Damage found at 3<sup>rd</sup> strake below sheerstrake No. 1 plate from  
ster punctured in way of aftermost frame space  
and port corner bar attachment of flat sternplate buckled.  
Temporary repairs now done. Patch about 2ft square welded over  
puncture in shell plate and landing edges on  
ster corner bar attachment in way electrically welded

RY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

CONDITION OF THE	Bulkheads	Engine Room Skylights	Copper, or Y.M. (State if on Felt.)
of Decks	Ceiling	Coal Bunkers, Openings, Covers, &c.	When fitted, Month Year
Fastenings	Cement or Asphalt	Oil Bunkers	Boats
Plating	Rudder	Scuppers	Masts, Yards, &c.
in way of sidelights	Steering gear and its connections	Cargo Hatchways	Condition, how ascertained
Frames	Windlass	Hatches	(State if wedges removed)
inals	Have pumps been examined and found effi- cient?	Planking	Equipment letter
ees	Have Sluice Valves been examined and found effi- cient?	Caulking	Anchors, No. of
Bottom Plating	Have Watertight Doors been examined and found efficient?	Treenails	Cables (State if now ranged)
Tanks been examined internally	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stems	length mean diam.
Tanks been tested?	Air and Sounding Pipes	Transoms, Pointers & Crutches	(on board)
	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	Rule length size
		" " at other places	Chain Locker
		Stringers, Clamps & Shelves	Hawsers & Warps
		Salting (State if examined.)	Standing and Running Rigging
			Sails

## General Observations, Opinion as to Class, Recommendation, &amp;c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

This vessel is eligible in my opinion to remain as classed  
without fresh record of survey, subject to permanent repairs being  
effected to aftermost plate in port side 3<sup>rd</sup> strake below sheerstrake  
together with stern boundary bar in way at first convenient

Fee (per Section 29) £ : : Fees applied for, 16-10-1940  
Damage or Repair Fee (if any) £ 3 3 : - Received by me, 23-10-1940  
Expenses (if chargeable) £ : :  
Surveyor's Fee (if any) £ : :  
Surveyor to Lloyd's Register of Shipping.

Committee's Minute

Character Assigned

FRI 8 NOV 1940

AS now

Lloyd's Register  
Foundation

W1156 0123