

1

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME Steel Screw M.S. "SAN CASIMIRO" Report _____ Gls. _____ No. 57790**For the CHIEF SHIP SURVEYOR** ~~XXXXXXXXXXXXXXXXXXXXXXXXXXXX~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey _____ First Entry _____ When due _____

*100AL 'Carrying Petroleum in bulk'

1 Dk. 2nd Dk. clear of cargo tanks 'Longitudinal framing at bottom and
at deck'

Cell. DBuE 69' 164t, DTf 25' 292t, PPT 140t, APT 89t.

FK, 15 BH, Lloyd's A & CP.

P 90', B 41', F 66'

Machy. aft.

This ship is generally similar to "SAN CONRADO"



© 2020

Lloyd's Register
Foundation

W1138-0090