

W1139 - 0049

Chief Surveyors _____ Received from Chief Surveyors _____

EL'S NAME Stl Se "QUERCUS" Report Lnk No. 18539**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/93.)

e of Survey 1st Entry When due _____ Revised Rule _____

✦ 100 A. I. (Steel)

1 D* (Stl)

Cell D.B a. v E 108', f 140' 631t, A.P.T. 76t.

F.K, 5 B.H, pt Cen, Lloyd's A + CP.

P 29', B 93', F 31'.

is concluded the thickness of the bottom ^{plates} at the ends of the vessel is as approved, but the surveyor should be requested to state if this is so.



© 2020

Lloyd's Register
Foundation8/1
9.5.26.