

1

Sent to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME TWEED Report LIV. No. 115715For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey DAMAGE When due.....

Subject to indented No 1 shell plates in 3rd, 4th + 5th strakes below sheer (P.S.) + framing in way being dealt with at the first convenient opportunity, to vessel being specially examined at next dry docking (bomb explosion) and to (a tower anchor and 45 fathoms of chain cable being supplied)

was
18.3.41

It takes
Red



© 2020

Lloyd's Register
Foundation

W1139-0001

General Observations, Opinion as to Class, Recommendation, etc.

Make clear whether any and if so, what alterations are proposed to be made to the existing classification and conditions of the vessel

in the Register Book