

3 - NOV 1939

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME "VICTOR ROSS". Rpt. Bel. No. 2480.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The Belfast Surveyors report the vessel placed in dry dock, bottom coated and minor repairs effected.

On account of damage through striking an unknown object shell plate G4 from aft, port side in way of No.8 wing tank found slightly set in, together with framing in way, but efficient.

The Surveyors recommend repairs at the Owners' convenience

It is submitted the vessel appears worthy to remain as classed with record of survey 10,39, subject as recommended,

100A1 }
10,39 Bel. } -subject etc.
"Carrying pet. in bulk"

way
1-11-39



© 2020

Lloyd's Register
Foundation