


of "Commander Horton"

Hul. Rpt. 28358.

It is submitted that the Hull Surveyors should be requested to state whether the bilge injection is connected to the circulating pump as in the case of the sister vessel "Commander Holbrook"
Hul. Rpt No 28310.

L-18/3/15



© 2020

Lloyd's Register
Foundation