

121 AUG 1942

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME _____

"DORSET"

Report _____

Liv. _____

No. 118191

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/92.*)

Nature of Survey _____

Damage.

~~Damage~~

Subject to permanent repairs to indented shell plates Nos.5 & 6 from aft in 2nd strake below sheer (s.s.) together with framing in way and to (pierced and scored) port quarter plating at the Owners' convenience and to the vessel being specially examined at the next dry docking on account of underwater explosion.

W1143-0002

18.5.42