

For the information of Surveyors and the Committee only.

Received at ..... Office, ..... 19

## Lloyd's Register of Shipping.

(Report on Machinery, No. .... Port .....

No. 4844

## ENGINE or BOILER VALVES or CONNECTIONS.

I have to report that the Details, as herein described, manufactured by Messrs. Chas McKil Ltd of Glasgow for the Engines or Boilers No. 534 being constructed by Messrs Workman Clark Ltd of Belfast have been inspected by me as set forth below, and found to be, so far as can be seen, sound and free from defects.

These have been despatched to Messrs Workman Clark Ltd Belfast

Stamp Mark.

LLOYD'S TEST.

No. 4844CSFChas. J. PorterGlasgow 2/5/1934

Number and Description.

4. Plain Air Receiver Ends. 5'-9" Dia x 1 3/16 thick  
4. Flanged do do 5'-9" Dia x 1 9/16 do.  
with M. H. Doors fitted.

Hydraulic Test:  
lbs. per square inch.

Other Tests, if any.

Dates when Inspected.

1/5/34 to 21/4/34

2m, 10, 20,

If comprising shell, Dia. as per rule } front ..... Pitch in outer vertical rows } Dia. of tube holes FRONT } stay .....



© 2021

Lloyd's Register  
Foundation

W1143-0025