

April 16, 1942

The Principal Surveyor
New York

S/S "JOSEPH W. CUDAHY"
N.O. Rpt. 5503

Dear Sir:

I regret that I overlooked the instructions in Circular No. 1707A after examining the E/W. repairs to the stern frame in the case of above vessel, and I have to inform you, that in my opinion this item may be deleted from the S.R. list.

Your remarks regarding the advisability of disconnecting worn chain cable, have been carefully noted.

Yours very truly,

P. F. Balfour

PFB:RMF



© 2020

Lloyd's Register
Foundation

W1145-0108