

1st S.S. No. 1, due 7, 41, partly held.
(Bower anchor & 45 fms. chain cable to supply.)

11

by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

10 MAR 1942

L'S NAME

LOCH DON

Rpt. HUL.

No. 51517

remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

of Survey

Docking

The

Hull

Surveyors report this vessel placed in

dry dock, bottom cleaned and coated, ~~repairs to~~

and minor repairs effected *to double plated stream lined mudder by electric welding.*

It is submitted the vessel appears worthy to remain as
classed with record of survey 2,42. as recommended.

100 A.I. } Subject etc.
2,42 HUL.

Tonnage Opening Closed '41 (W.E.)



© 2020

Lloyd's Register
Foundation

W1147-0057